

Illig (Ed.)
Peter Schwarzmann

Thermoforming

A Practical Guide



Bonus

HANSER

Illig
Peter Schwarzmann

Thermoforming

A Practical Guide

2nd edition

Hanser Publishers, Munich

HANSER
Hanser Publications, Cincinnati

The editor:

ILLIG Maschinenbau GmbH & Co. KG, Robert-Bosch-Strasse 10, 74081 Heilbronn, Germany

The author:

Peter Schwarzmann, ILLIG Maschinenbau GmbH & Co. KG, Heilbronn, Germany

Distributed in the Americas by:

Hanser Publications

6915 Valley Avenue, Cincinnati, Ohio 45244-3029, USA

Fax: (513) 527-8801

Phone: (513) 527-8977

www.hanserpublications.com

Distributed in all other countries by:

Carl Hanser Verlag

Postfach 86 04 20, 81631 Munich, Germany

Fax: +49 (89) 98 48 09

www.hanser-fachbuch.de

The use of general descriptive names, trademarks, etc., in this publication, even if the former are not especially identified, is not to be taken as a sign that such names, as understood by the Trade Marks and Merchandise Marks Act, may accordingly be used freely by anyone. While the advice and information in this book are believed to be true and accurate at the date of going to press, neither the authors nor the editors nor the publisher can accept any legal responsibility for any errors or omissions that may be made. The publisher makes no warranty, express or implied, with respect to the material contained herein.

The final determination of the suitability of any information for the use contemplated for a given application remains the sole responsibility of the user.

Cataloging-in-Publication Data is on file with the Library of Congress

All rights reserved. No part of this book may be reproduced or transmitted in any form or by any means, electronic or mechanical, including photocopying or by any information storage and retrieval system, without permission in writing from the publisher.

© Carl Hanser Verlag, Munich 2019

Editor: Dr. Mark Smith

Production Management: Jörg Strohbach

Coverconcept: Marc Müller-Bremer, www.rebranding.de, Munich

Coverdesign: Stephan Rönigk

Typesetting: Kösel Media GmbH, Krugzell

Printed and bound by Druckerei Hubert & Co GmbH und Co KG BuchPartner, Göttingen

Printed in Germany

ISBN: 978-1-56990-708-5

E-Book ISBN: 978-1-56990-709-2

Preface to the 2nd English Edition

The success of the 3rd expanded German edition has resulted in ILLIG Maschinenbau professionally translating the book into English. This 2nd English edition of the work shows the extensive technological innovations in thermoforming processes and new applications that have arisen since the first edition was published. A highlight is the decoration of moldings in Chapter 19 “Decoration and thermoforming”, which describes the innovative process of in-mold labelling (also IML-T in-mold labelling in thermoforming) and other design possibilities of molded parts. The revised English edition is intended to create and support even more thermoforming experts worldwide. The author, Mr Peter Schwarzmänn, has checked and approved the English content. Thank you for your intensive support.

Heilbronn, September 2018

ILLIG Maschinenbau GmbH & Co. KG

■ Preface to the 3rd German Edition

The supplementary material added to the translations into English, French, Chinese, Russian and Spanish has combined with advances in thermoforming technology and the demand for more information regarding tool technology to inspire the substantial revisions and new material incorporated in this 3rd edition. The author, Mr Peter Schwarzmänn, has consistently kept sight of this work’s original objective while expanding its scope.

Heilbronn, June 2015

ILLIG Maschinenbau GmbH & Co. KG

■ Preface to the 2nd German Edition

The success of the 1st edition, which has also been translated into the English, French, Chinese and Russian languages, has combined with extensive technological innovations in thermoforming processes and new applications to inspire this 2nd edition with its comprehensive revisions and new material. The original objective of this work

Heilbronn, October 2008

ILLIG Maschinenbau GmbH & Co. KG

■ Preface to the 1st German Edition

The manufacturing processes employed in industrial thermoforming are currently finding extensive use in an array of applications that could hardly been conceived of just a few decades ago. Thermoforming has expanded beyond its traditional sectors, such as vacuum forming of panels for displays, refrigerators and automotive components, into pressure forming to produce packaging materials, ultimately conquering a considerable market share. Continuous improvements in thermoplastic materials have combined with ultra-modern machinery and tools to create increased production counts featuring greater precision in the formed parts. Originally situated in the realm of manually executed crafts, thermoforming has evolved into an established production process relying on consistent application of scientific insights from material sciences, supported by technology for measurement and closed-loop control. Reproducible process parameters allow application of procedures for industrial use in high-performance assemblies. In addition to numerous articles published in magazines, for several decades ILLIG Maschinenbau GmbH & Co. KG has also been disseminating the basics of thermoforming in training courses. What has been missing is a comprehensive compilation of the basic processes and procedures for the student as well as the engineer or technician who is currently active in the field, in a work capable of simultaneously serving as an introduction to the discipline for both groups by furnishing basic knowledge as well as more extensive expertise concerning individual questions. The objective of “Thermoforming: A Practical Guide” is to close this gap by fulfilling the stated objectives. It provides comprehensive descriptions extending beyond thermoplastic materials to embrace all of the steps in the thermoforming process along with an array of machine types and the basics for building molds and tools, explained with examples from actual practice. The genesis of this book is closely connected with the 50-year history of ILLIG itself. Accordingly, numerous insights, suggestions and experiences have entered this book, and I extend my particular gratitude to the author, Mr Peter Schwarzmann, for providing a detailed portrayal of this subject matter. I would like to thank Mr Günter Kiefer, who has served as the head of the Development and Engineering Department at ILLIG for many years, and Prof Dr Günther Harsch for their critical proofreading of the manuscript, and for their numerous suggestions for improvements and additions. The publisher and the author hope that “Thermoforming: A Practical Guide” will serve as a source of convenient access to the essentials of thermoforming and furnish useful assistance in resolving problems when they arise.

Heilbronn, January 1997

Adolf Illig

Contents

Preface to the 2nd English Edition	V
Preface to the 3rd German Edition	V
Preface to the 2nd German Edition	V
Preface to the 1st German Edition	VI
1 Introduction	1
2 Basic principles and terminology in thermoforming	5
2.1 Process sequence	5
2.2 Positive and negative forming	6
2.3 Vacuum and pressure forming	8
2.3.1 Differences between vacuum and pressure forming	8
2.3.2 Application for pressure forming	9
2.4 Forming pressure, contour-molding pressure, and contour definition	10
2.5 Preblow, presuction, pressure equalisation, air injection	12
2.6 Chill marks and blemishes	13
2.6.1 Chill marks on positively formed parts	14
2.6.2 Chill marks on negatively formed parts	17
2.6.3 Causes of chill marks	19
2.6.4 Options for reducing chill marks	19
2.6.5 Results of chill mark formation	20
2.6.6 Use of typical wall-thickness distribution in chill marks with snaps on clamshell packages	21
2.6.7 Conclusions with regard to chill marks	22
2.6.8 Blemishes and markings	22
2.7 Wrinkle formation during thermoforming	23
2.7.1 Wrinkle formation sequence in positive forming	24
2.7.2 Wrinkle formation in negative forming	26
2.7.3 Wrinkle formation on surfaces	27

2.8	The tool set	28
2.9	Forming surface, intake surface, clamped edge	29
2.10	Downholder, upholder	30
2.11	Forming and stretching ratio	31
2.12	Draft angles	32
2.13	Vent cross-sections	33
2.14	Calculating wall thickness	33
3	Semi-finished thermoplastic materials	35
3.1	Elements and structure of thermoplastic materials	35
3.2	Absorption of moisture in semi-finished product	36
3.3	Response during heating	37
3.4	Expansion and sag	39
3.5	Forming temperature ranges	41
3.6	Friction properties in thermoforming	42
3.7	Contour definition	44
3.8	Molding shrinkage in thermoforming	45
3.9	Free shrinkage of semi-finished products	51
3.10	Effects of stresses in the extruded semi-finished product	55
3.11	Electrostatic charge	59
3.12	The visco-elastic properties of thermoplastic materials during thermoforming	60
3.13	Properties during cooling	62
3.14	Tolerances of semi-finished products	62
3.15	Manufacturing process for thermoplastic semi-finished products	63
3.16	Table for the thermoformer	67
3.17	Thermoplastics for thermoforming	71
3.17.1	Polystyrene (PS)	71
3.17.2	High-impact polystyrene (HIPS)	72
3.17.3	Styrene butadiene styrene block copolymer (SBS)	73
3.17.4	Oriented polystyrene (OPS)	74
3.17.5	Acrylonitrile butadiene styrene copolymer (ABS)	75
3.17.6	Acrylic styrene acrylonitrile copolymer (ASA)	76
3.17.7	Styrene acrylonitrile copolymer resin (SAN)	77
3.17.8	Polyvinylchloride (PVC-U)	78
3.17.9	Polyethylene, high-density (PE-HD)	79

3.17.10	Polypropylene (PP): Detailed presentation	80
3.17.11	Extruded polymethyl methacrylate (PMMA ex)	95
3.17.12	Cast polymethyl methacrylate (PMMA g)	96
3.17.13	Polycarbonate (PC)	98
3.17.14	Polyamide (PA)	99
3.17.15	Polyethylene terephthalate, PET: Detailed presentation	100
3.17.16	Polysulfone (PSU)	107
3.17.17	EPE and EPP foamed materials	108
3.17.18	Bioplastics in thermoforming	109
3.17.18.1	Biodegradable plastics from renewable raw materials	110
3.17.18.2	Non-degradable bioplastics	115
3.17.19	Multilayer, barrier and composite semi-finished materials ..	116
3.17.20	Other materials	125
3.17.21	Brand names	126
4	Heating technology in thermoforming	127
4.1	Radiant heaters	127
4.1.1	Heat-transfer concept with infrared radiation	127
4.1.2	Heat quantity transferred by radiation	129
4.1.3	Homogeneous heating with radiant heaters	135
4.1.4	Ceramic, quartz and halogen heaters in comparison	142
4.2	Reproducibility of heating results in radiant heaters	145
4.2.1	Assessing reproducibility	145
4.2.2	Compensation for uncontrollable external influences on the heating process	149
4.2.3	Power control and temperature control in heaters	150
4.3	Contact heaters	151
4.4	Convection heaters	153
4.5	Minimum heating time, effective heating time and residence time ...	154
4.5.1	Effect of heating time on thermoforming response	154
4.5.2	Positive effect of residence time	155
4.5.3	Negative effect of residence time	155
5	Heaters in sheet-processing machines	157
5.1	Basic principles of heating with isothermal control	158
5.1.1	Technical terminology	158
5.1.2	Details regarding temperature control with ceramic heat elements	161
5.1.3	Advantages of heating systems with closed-loop control provided by pilot heater elements	162

5.2	Joystick distribution of the heating pattern	162
5.3	Multi-positional control	164
5.4	Heater-element temperature control with superimposed position in percent	166
5.5	IR-sensor (pyrometer) for monitoring temperature and closed-loop control of heaters	167
6	Heaters in automatic roll-fed machines	169
6.1	General information	169
6.2	Heaters regulated by pilot heater elements in automatic roll-fed machines	170
6.2.1	Heater with longitudinal control of row temperatures	170
6.2.2	Heater panel with temperature control governing total array	171
6.2.3	Heater with transverse row control	172
7	Heating multicoloured and preprinted materials using IR heaters	173
7.1	General information	173
7.2	Selection of infrared heaters	173
8	Thermoforming process on sheet-processing machines	177
8.1	Positive forming	178
8.1.1	Positive forming with mechanical prestretching	178
8.1.2	Positive forming with preblow	179
8.1.3	Positive forming with preblow against a board	182
8.1.4	Positive forming with presuction and unreeling of the blister on the mold	183
8.1.5	Positive forming with presuction in a vacuum/pressure box .	184
8.1.6	Application of corner blow nozzles with positive forming ...	185
8.2	Negative forming	186
8.2.1	Negative forming without plug-assist tool	186
8.2.2	Negative forming with plug-assist tool	187
8.3	Positive-negative forming	189
8.4	Twin-chamber method (3K method)	190
8.5	Twinsheet forming	191
8.5.1	Universal rules for twinsheet forming on series twinsheet forming machines	192
8.5.2	Twinsheet forming process, UA machine with hand loading .	193
8.5.3	Machine versions for twinsheet forming	196

8.6	Adhesive lamination	198
8.6.1	General information	198
8.6.2	Lamination process	199
9	Thermoforming process on automatic roll-fed machines, punching station with blade cut	203
9.1	Concept of process sequence at the forming station	203
9.2	Machine equipment with an effect on the forming procedure	207
9.3	Selecting the correct forming procedure and tool configuration	208
9.4	Information regarding ways to influence wall thickness distribution .	209
10	Thermoforming process on automatic roll-fed machines, forming and punching tools with shear cuts	215
10.1	Geometrical motion patterns of the forming and punching station ...	215
10.2	The special features of the mechanical cam control	217
10.3	Flow chart for a forming station using forming and punching tool with negative forming	218
10.3.1	Forming-air reduction	219
10.3.2	Downholder control	219
10.4	Flow chart for a forming station using forming and punching tool with shear cut for positive forming	220
11	Special procedures using combined forming and punching tools in automatic roll-fed machines	221
11.1	Applying linings to dimensionally stable containers	221
11.2	Labelling in the mold (IML In-Mold Labelling)	223
11.3	Forming and punching tool for rimless formed parts	226
11.4	Thermoforming hollow-base cups	227
11.5	Thermoforming with mold and countermold	228
12	Thermoforming transparent parts	229
12.1	Generally applicable rules for forming transparent parts	229
12.2	Special considerations for molding with sheet-processing machines .	231
12.3	Special considerations for forming with automatic roll-fed machines .	232
12.4	Sample procedures – Production of transparent parts	236
12.5	Special production process for transparent parts	241

13	Thermoforming preprinted materials	243
13.1	General information	243
13.2	Determining distortion-printing image	246
14	Cooling the formed parts	251
14.1	The demolding temperature	251
14.2	Influencing factors affecting cooling times	252
14.3	Cooling with the mold	253
14.4	Cooling with air	253
14.4.1	Current technology for air cooling in sheet-processing machines	255
14.4.2	Reducing the mold temperature in conjunction with colder cooling air	257
15	Demolding	261
16	Stacking parts	265
16.1	General information	265
16.2	Stacking formed parts with changing stacking lugs	271
17	Finish-processing on thermoformed parts	273
17.1	Separating, cutting	273
17.2	Deburring	276
17.3	Connecting	276
17.4	Recycling	278
18	Punching thermoformed parts	279
18.1	Blade cut	279
18.2	Shear cut	286
18.3	Comparisons of blade and shear cuts	293
18.4	Factors affecting the punching process	296
18.5	Angel-hair formation	297
18.5.1	Reduction of angel-hair formation with blade cut	301
18.5.2	Reduction in angel-hair formation with shear cut in forming and punching tool	302
18.6	Rough-edged cuts – Die drool	304
18.7	Punching forces	306

18.8	Conclusion	308
18.8.1	Blade-cut tools - Punching tools for separate punching station	308
18.8.2	Shear-cut tools for separate punching station	309
18.8.3	Forming and punching tools with blade cut	310
18.8.4	Forming and punching tools with shear cut	310
18.9	Related cutting procedures	311
19	Decoration and thermoforming	315
19.1	Illustrations	320
20	Distortion in thermoformed parts	329
20.1	Demonstrations of influences on distortion	329
20.2	Effect of thick points	331
20.3	Effect of tension in the semi-finished material	331
20.4	Distortion in a labelled formed part	332
20.5	Distortion of the clamped flange on a rectangular formed part	332
20.6	Distortion with anisotropic contraction	333
20.7	Conclusion, causes of distortion	334
20.8	Tips and information regarding distortion	335
21	Thermoforming tools	337
21.1	Terminology and definitions	337
21.2	Materials for the forming segment	338
21.3	Help for the tool material and version selection	342
21.4	Positive or negative forming?	343
21.5	Design configuration of the forming surface	344
21.6	Processing shrinkage: Who supplies the data?	348
21.7	Determining the size of the material	349
21.8	The substructure	350
21.8.1	Illustrations of structural concepts for tools	353
21.8.2	Adjustable substructures for sheet-processing machines	357
21.8.3	Difference between invariable format and adjustable substructure	358
21.9	Design details for thermoforming tools	359
21.9.1	Sidewall drafts	359
21.9.2	Surface roughness	360

21.9.3	Radii	363
21.9.4	Tool venting, air-discharge cross-sections	364
21.9.5	Cavities	368
21.9.6	Materials for plug-assist tools	368
21.9.7	Plug-assist tool contours for negative forming	370
21.9.8	Plug-assist tool for positive tools	374
21.10	Tool with undercut	375
21.10.1	Demolding undercuts without detachable parts	375
21.10.2	Detachable parts (slider) for demolding undercuts	375
21.11	Tool design for flat formed parts with low stretch	376
21.12	Tools for forming transparent parts	377
21.13	Tools for twinsheet forming	379
21.14	Tools for sheet-material hinges and snap couplings	385
21.15	Forming and punching tools with shear cut in automatic roll-fed machines	391
21.16	Forming and punching tools with knife cut in automatic roll-fed machines	394
21.17	Preventative maintenance on forming tools	407
22	Temperature control for thermoforming tools	411
22.1	General information	411
22.1.1	Temperature control terminology	411
22.1.2	Effects of tool temperature	412
22.1.3	When is it possible to dispense with tool temperature control?	412
22.2	Temperature-control media	413
22.3	Materials for thermoforming tools suitable for temperature control ..	414
22.4	Cooling-circuit versions	414
22.4.1	Examples of circuits in thermoforming machines	415
22.5	Cooling process	417
22.6	The cooling requirements of a thermoformed part	418
22.6.1	The enthalpy diagram	418
22.6.2	Enthalpy tables	419
22.6.3	Required cooling power for the tool	419
22.7	Design configuration of temperature-control system for a forming tool	420
22.7.1	Material quantity being cooled (material throughput)	421
22.7.2	Required cooling power during production	421

22.7.3	Cooling-water requirement for tool cooling	422
22.7.4	Contact surface required for the cooling water	423
22.7.5	Total length of cooling passages	424
22.7.6	Water velocity	424
22.7.7	Resulting pressure drop in the tool	425
22.7.8	Pressure loss when connecting the forming tool in the machine	427
22.8	Pressure loss in the machine's pipework	429
22.9	Pressure loss in overall temperature-control circuit	430
22.10	Testing the pumping capacity of the connected temperature control or cooling equipment	431
22.11	Assessing the test result	432
22.12	Design configuration options in heat transfer	433
22.13	The effects of air cooling on tool cooling	433
22.14	Preventive maintenance	434
23	Energy consumption in thermoforming	437
23.1	General information	437
23.2	Specific energy consumption in thermoforming	438
23.3	The share of energy costs as a proportion of the manufacturing costs for moldings	441
23.4	Options for reducing the specific energy consumption	444
23.4.1	Saving energy with electric drive units	446
23.4.2	Reduction of energy use in pressure forming	448
23.4.3	Reduction in the volume filled with compressed air, forming air reduction	449
23.4.4	Effects of pressure level	450
23.4.5	Reducing energy consumption during heating	454
23.4.6	Cost reductions with new vacuum pumps	457
23.4.7	Short cooling times reduce energy costs	457
23.4.8	Insulation of pipes?	459
23.4.9	Application of fresh-air coolers instead of refrigeration units with compressor	459
23.4.10	Offset heater starting time reduces price of power	459
23.4.11	Using energy reduction for extended downtime periods	460
23.4.12	Using the machine's basic settings	460
23.4.13	Regular periodic maintenance	460
23.4.14	Dynamic process optimisation	461
23.4.15	The energy consumption display	461
23.4.16	Energy consumption measurements in production	461

24	Thermoforming faults	463
24.1	Geometrical configuration errors on the formed part	463
24.2	Faults in the material	468
24.3	Selection of the correct thermoforming machine	470
24.4	Errors during installation of the thermoforming machine	471
24.5	Faults in the thermoforming tool	471
24.6	Errors during break-in new thermoforming tools	473
24.7	Errors during sample article inspections	474
24.8	Errors during heating with infrared radiators	474
24.9	Pipe and tube cross-sections for air and vacuum	475
24.10	Preventing wrinkle formation	476
24.11	Fault diagnosis in thermoforming	477
Index		489

Thermoforming is understood as the process of reshaping thermoplastic materials at high temperatures in order to create formed parts.

The illustration in Figure 1.1 shows the concept of a thermoforming process relying on vacuum forming.

The stages in this process are:

- Heating the semi-finished material to its forming temperature within the elastoplastic range
- Endowing it with a shape defined by the thermoforming tool
- Cooling under forced retention, which continues until a temperature at which the formed part achieves geometrical stability is reached
- Demolding the geometrically stabilised formed part

The finished part's wall thickness is defined by the ratio of elongation in the generated surface to the initial surface area. The wall-thickness distribution in the formed part is primarily determined by the mold and the forming procedure.

The contour definition – equating with the accuracy with which the mold's contours are reproduced – is primarily determined by the temperature-sensitive strength of the semi-finished product during the forming process and the effective contact pressure generated between the semi-finished product and the surface of the mold.

The formed part is usually cooled on one side through contact with the mold and on the other side through atmospheric or forced-air cooling.

This process is usually followed by various subsequent treatments, such as cutting, welding, adhesive bonding, hot sealing, painting, metallising and flocking.

The terms “vacuum forming” and “pressure forming” are also employed. This also refers to molding using vacuum and compressed air.




Figure 1.1 Concept of thermoforming

Advantages and disadvantages of thermoforming

A manufacturing process will only prove successful provided that it can produce parts of equal quality but at less expense, or in better quality at the same cost. There are also applications in which injection molding and blow molding compete with thermoforming. Thermoforming is usually without competition in the realm of packaging technology, except in those cases in which cardboard and paper are utilised as alternate packaging materials.

The essential benefits of thermoforming are:

- Formed parts with extremely thin walls, such as packaging units, can be manufactured using semi-finished materials with a high melting viscosity, although such parts require granulate with an extremely low melting viscosity for production with injection molding – provided that they can be manufactured at all.
- The smallest thermoformed parts assume sizes on the order of those used for medicinal tablets and button cell batteries. Large formed parts, such as garden ponds, reach sizes extending to between 3 and 6 metres in length. Formed parts in dimensions embracing multiple square metres can be produced without problems, while the process technology imposes no inherent limits on the size of the formed parts or the gauge of the semi-finished material.
- Semi-finished materials with gauges ranging from 0.05 to 15 mm are used, with foamed materials extending to 60 mm.
- Application of multilayer materials renders it possible to produce formed parts with combinations of properties regarding flexural and tearing strength, surface gloss, haptic compliance, anti-slip properties, suitability for sealing, UV resistance, barrier characteristics, embedment of granulate in a layer below the surface, inclusion of layers incorporating fibres, etc. When the individual layers fail to furnish adequate adhesion, then intermediate layers can be incorporated to facilitate bonding.

- Thermoforming is suitable for processing foamed materials, fibre-reinforced materials and thermoplastic materials with laminated textiles as well as preprinted semi-finished products.
- The stretching representing an intrinsic element in the process enhances the formed part's mechanical properties by promoting orientation.
- Owing to forming contact on just one side, thermoforming molds are more economical than (for instance) injection molding tools, which rely on bilateral form contact to define wall thickness.
- The modest tooling costs represent a benefit of using thermoforming for limited production runs. Thermoforming's salient assets in large production runs consist of the minimum wall thicknesses that can be achieved and the high production rates reached by the thermoforming machines.
- Thermoforming machines featuring modular design configurations allow adaptation to the required production rate.
- Waste materials such as the skeletal sheet webs and clamped edge strips are granulated, only to return to the processing cycle when recycled during manufacture of the semi-finished product.

The materials used in thermoforming assume the form of semi-finished products consisting of sheet material in rolls or formed into pre-cut sheets that are produced from granulate or powder in an initial shaping procedure. This entails supplementary expenditures relative to injection molding for the initial material.

In thermoforming, the semi-finished product is only in contact with one side of the thermoforming tool as an intrinsic characteristic of the process. It is for this reason that the formed part represents an accurate reproduction of the mold's contours on only one of its sides. The contour on the opposite side is produced by the resulting elongation.

Future perspectives

Within the plastics-processing sector, it is thermoforming that represents the realm promising the highest growth rates. This applies to formed parts destined for technical applications as well as packaging.

- In its guise as a process that relies on careful craftsmanship and extensive experience, thermoforming is currently in a state of transition as it evolves into a highly controlled process.
- Sensors combine with closed-loop control technology to allow automation of the thermoforming process.
- Recycling waste materials from production, granulation and admixture to form new materials has long been the state-of-the-art in technology.

- Natural “bio” synthetics are becoming progressively more economical. The thermoforming process is predestined to apply these materials for thin-wall packaging with ever-increasing emphasis.
- Application of multilayer materials allows production of parts featuring a wide spectrum of potential applications.
- Meanwhile, in high-wage countries, the trend is continuing toward increased automation, integration of subsequent processes and higher productivity.

2

Basic principles and terminology in thermoforming

■ 2.1 Process sequence

The thermoforming process consists of the following individual steps:

1. **Heating** the material to forming temperature
2. **Preforming** the heated material with prestretching
3. **Contour molding** the formed part
4. **Cooling** the formed part
5. **Demolding** the formed part

Heating

See Chapter 4 “Heating technology in thermoforming”.

Preforming

Various options for preforming are in existence, i. e.:

- Prestretching with preblow, i. e., bubble formation with compressed air
- Prestretching with presuction, i. e., bubble formation with vacuum
- Mechanical prestretching using a plug assist, also called plug-assist tool or upper plug
- Mechanical prestretching using the form itself
- Combination of the above-cited prestretching options

Contour molding

Examples of contour molding:

- Contour molding with vacuum (vacuum-forming machines)
- Contour molding with compressed air (pressure-forming machines or vacuum-forming machines with locked molds)

- Contour molding with compressed air and vacuum (pressure-forming machines with supplementary vacuum connection or vacuum-forming machines with locked molds)
- Contour molding with stamping. Stamping allows bilateral definition of the tool's contours. Applied for foamed materials, more rarely for stamping and calibrating edges.

Cooling

Cooling options for the formed part, based on machine type:

- Cooling through contact with the forming tool (usually unilateral)
- Cooling with air in various versions:
 - Air is ingested from the environment with suction (standard)
 - A building-installed system delivers cool air to the fans
 - Water spray mist is blown into the air current; as this spray mist evaporates in the air stream, it cools the air. At air velocities of approximately 10 m/s and a distance between fan and formed part of roughly 1.5 m, the air cools by about 10 °C. (Notice: When the airspeeds are too high, the formed parts become wet because adequate time for evaporation of the water spray mist is not available.)
- Free cooling in the air if procedure is without mold.

Demolding

Demolding proceeds once the thermoplastic material has cooled below its pliability temperature, i. e., it is stiff enough.

■ 2.2 Positive and negative forming

Positive forming (Figure 2.1, a):

- Molding reflecting the outer contour of the form (simplified definition)
- The return forces in the material and the contour-molding forces are effective in the same direction.

Negative forming (Figure 2.1, b):

- Molding reflecting the inner contour of the form (simplified definition)
- The return forces in the material and the forming forces are mutually opposed.




Figure 2.1 Positive and negative forming
a) Positive forming (schematic)
b) Negative forming (schematic)
X = molded dimension from mold

Table 2.1 Comparison between positively and negatively formed part

Property	Positively formed part	Negatively formed part
Accuracy of molded image in the formed part	On the inside	On the outside
Dimensions (in drawing)	On the inside	On the outside
Thick edge sector	Edge thinned by stretching	Edge remains practically unstretched; wall thickness equals initial thickness
Thickest location*	On base	On edge
Thinnest location*	On edge (transition to sidewall)	On base (transition to sidewall)
Risk of wrinkle formation	At corners contiguous to edge	No wrinkle formation

* If molded without preforming, with relatively low stretching ratio




Figure 2.2 a) Positively formed part with wrinkles toward the edge and chill marks at the corners marking the transitions between base and sidewalls
b) Negatively formed part without wrinkles and consistent edge thickness around entire periphery

■ 2.3 Vacuum and pressure forming

Depending upon the forming pressure available for the thermoforming process, the standard reference is to vacuum or pressure forming.

During vacuum forming, the vacuum pump supplies the vacuum applied to the heated material which has been heated, as well as preformed as required, to suck it onto the surface for the mold. This produces a forming pressure corresponding to the difference between atmospheric pressure and the vacuum generated by the vacuum pump, i.e., of a maximum of approximately 1 bar (100,000 Pa).

During pressure forming, compressed air pushes the heated material against the surface of the tool. This process relies on a sealed compressed-air chamber, into which the compressed air can flow as forming air.

With regard to the maximum forming pressure (also pressure of the forming air), various levels are available: up to 2.5 bar, 6 to 8 bar and special-duty machines with up to approximately 200 bar.

2.3.1 Differences between vacuum and pressure forming

Table 2.2 Comparison between vacuum and pressure forming

Property	Vacuum forming	Pressure forming	Comment
Forming temperature of the material	Higher	Lower	With the same contour definition, temperature differential roughly 20 °C
Sag	Higher	Lower	Determined by the material's temperature-sensitive strength
Friction between material and plug-assist tool	Higher	Lower	Friction increases with higher material temperature
Friction between material and mold	Higher	Lower	Friction increases with higher material temperature
Required forming force	Lower	Higher	Determined by the material's temperature-sensitive strength Attention to special cases: APET, CPET, lowest forming force at a specific temperature!
Contour definition	Lower	Higher	At same forming temperature
Wall thickness distribution	Worse	Better	Universal statement
Chill marks	Higher	Lower	Owing to friction/stiction
Thermal resistance of formed part	Lower	Higher	As the forming temperature increases, the residual stresses in the heated material decrease proportionately, with commensurate increases in thermal resistance
Cooling time	Higher	Lower	Owing to forming temperature
Cycle time	Longer	Shorter	Owing to cooling time

Table 2.2 Comparison between vacuum and pressure forming (*continued*)

Property	Vacuum forming	Pressure forming	Comment
Vent holes in mold	Larger individual cross-sections	Smaller individual cross-sections	Sample bores: - For HIPS: 0.8/0.5 mm, - for PP: 0.6/0.3 mm. Example of slots: - For HIPS: 0.5/0.3 mm, - for PP: 0.3/0.2 mm.
Tool costs	Lower	Higher	Differences: Pressure box for pressure forming, size and sum of vent bores and slots, overall stability of mold.
Tool weight	Lower	Higher	Owing to pressure box
Retention force of machine	Lower	Higher	If the mold has no locking mechanism
Energy consumption for contour molding	Lower	Higher	Universal statement for tools with “standard design”. Very substantial reductions in energy consumption for pressure forming are available through application of targeted solutions.
Manufacturing costs for small production runs	Lower	Higher	Generally applicable blanket statement
Manufacturing costs for large production runs	Higher	Lower	Generally applicable blanket statement

If the quality can be achieved with either vacuum or with pressure forming, and the machines for both are available, then a calculation of product manufacturing costs for the formed part will determine whether vacuum or compressed air should be used for forming.

2.3.2 Application for pressure forming

Packaging parts

- As a universal rule, articles that must be produced in large numbers, such as cups, lids, trays, packaging inserts, etc.
- For materials with which vacuum forming is accompanied by difficulties in the areas of transparency, wall-thickness distribution and contour definition:
 - PP in consideration of its low melt resistance (sag)
 - OPS owing to its low forming-temperature range
 - APET because its transparency and suitability for molding both decline as forming temperatures rise
- For preprinted sheet material owing to the low level of distortion in the printed image at low forming temperatures.

Parts for technical applications

- Parts in which an extremely high level of contour definition (extremely small radii) is demanded and the material cannot be formed with this level of precision using a vacuum, such as polycarbonate and cast acrylic glass.
- For particularly high demands for surface quality in formed parts.
- In general, if the forming force obtained with vacuum is not adequate.

Conclusion

Using pressure forming extends the borders of the realm of possibility.

Pressure forming always requires more complex tools, but always offers the advantage of shorter cycle times.

The energy consumption during pressure forming is generally higher than in vacuum forming. Minimum compressed-air consumption implemented with appropriate tool technology can allow increased pressure for the forming air, which makes it possible to reduce the material's forming temperature. The energy consumption must be calculated to determine whether increased tool expenditure for decreasing compressed-air consumption represents a worthwhile investment.

Vacuum forming is better for limited production runs because the tools are simpler – with the proviso that the formed parts display the demanded quality.

The manufacturing costs incurred in producing the formed parts in large production runs are usually more favourable than with vacuum forming. The production costs for the formed parts must be subjected to mutual comparisons as the basis for unambiguous conclusions.

■ 2.4 Forming pressure, contour-molding pressure, and contour definition

The forming pressure in a machine with vacuum forming corresponds to the difference between the atmospheric pressure on one side of the material and the vacuum that the vacuum pump is generating on the other side of the material. At sea level, the barometric pressure is approximately 1 bar (100,000 pascals), and this figure decreases by roughly 0.1 bar with each altitude increase of 1000 m. Thus the reshaping, or forming pressure (at sea level) will be about 1 bar with an as-new vacuum pump. At 1 m² A forming force of roughly 10,000 daN is thus exerted against the forming surface during vacuum forming. This corresponds to the total weight of approximately ten compact cars.

The contour-molding pressure as applied reshaping pressure of the material against the walls of the mold results from the forming pressure and the return tension in the material during stretching.

Within the mold, the positions indicated with (+) in Figure 2.3 are:

Resulting contour-molding pressure = Forming pressure + return tension in the material

Applicable to positions identified with (-) in Figure 2.3:

Resulting contour-molding pressure = Forming pressure - return tension in the material




Figure 2.3 Schematic representation of resulting contour-molding pressure as sum of forming and return force of a material

a) and b) Positive mold

c) and d) Negative mold

(+) Surfaces on the tool where the return forces in the material and the contour-molding forces are exerted in the same direction

(-) Surfaces on the tool where the return forces in the material and the finish-forming forces are mutually opposed during forming

The contour definition achieved in a specific section of the part will primarily depend on the type of plastic, the forming temperature and the resulting contour-molding pressure.

■ 2.5 Preblow, presuction, pressure equalisation, air injection

Preblow

Preblow (Figure 2.4) designates prestretching the semi-finished material by forming a bubble using positive pressure. The preblow pressure in most machines is a maximum of 0.03 bar.




Figure 2.4 Preforming with preblow (this is not possible in all thermoforming machines)

Presuction

Presuction (Figure 2.5) designates preforming the semi-finished material by forming a bubble using a vacuum.




Figure 2.5 Preforming with presuction (this is not possible in all thermoforming machines)

Above: Presuction in a blow box

Below: Presuction in a vacuum/pressure box

Pressure equalisation

Once the cooling time has elapsed following the forming process, but before air-assisted demolding starts, the forming pressure (vacuum or compressed air) is