



Metrology and Instrumentation

Practical Applications for Engineering and Manufacturing

Samir Mekid

ASME
PRESS

WILEY

Table of Contents

[Cover](#)

[Title Page](#)

[Copyright](#)

[Preface](#)

[About the Website Materials](#)

[Acknowledgments](#)

[About the Author](#)

[1 Fundamental Units and Constants in Metrology.](#)

[1.1 Introduction](#)

[1.2 Current Definitions of the Main SI Units](#)

[1.3 New Definition of Seven Base Units of the SI](#)

[1.4 Derived International System \(SI\) Units](#)

[1.5 SI Conversion](#)

[1.6 Fundamental Constants](#)

[1.7 Common Measurements](#)

[1.8 Principles and Practices of Traceability](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[2 Scales of Metrology.](#)

[2.1 Introduction to Practical Metrology across All Scales](#)

[2.2 Nanometrology](#)

[2.3 Standards](#)

[2.4 Micrometrology](#)

[2.5 Macroscale Metrology](#)

[2.6 Large-Scale Metrology and Large-Volume Metrology](#)

[2.7 Instruments Techniques](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[3 Applied Math and Statistics](#)

[3.1 Introduction](#)

[3.2 Scientific and Engineering Notation](#)

[3.3 Imperial/Metric Conversions](#)

[3.4 Ratio](#)

[3.5 Linear Interpolation](#)

[3.6 Number Bases](#)

[3.7 Significant Figures, Rounding, and Truncation](#)

[3.8 Geometry and Volumes](#)

[3.9 Angular Conversions](#)

[3.10 Graphs and Plots](#)

[3.11 Statistical Analysis and Common Distributions](#)

[3.12 Formulation of the Standard Uncertainty and Average of Indirect Measurements](#)

[Multiple Choice Questions of this Chapter](#)

[Notes](#)

[4 Errors and their Sources](#)

[Introduction](#)

[4.1 Definition of the Error and Their Types](#)

[4.2 Measurement Characteristics](#)

[4.3 Propagation of Errors](#)

[4.4 Sources of Errors](#)

[4.5 Error Budget](#)

[4.6 Error Elimination Techniques](#)

[4.7 Model of Errors in CNC Using HTM](#)

[4.8 Case Study of Errors Budget](#)

[4.9 Solved Problems](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[5 Measurement and Measurement Systems](#)

[5.1 Introduction](#)

[5.2 What Can Be Standard in a Measurement?](#)

[5.3 Definitions of Key Measurement Components](#)

[5.4 Physical Measurement Process \(PMP\)](#)

[5.5 Difference between Number and an Analysis Model](#)

[5.6 Measurement Methods](#)

[5.7 Instrumentation for Measurement](#)

[5.8 Non-Portable Dimensional Measuring Devices](#)

[5.9 Metrology Laboratory Test for Students](#)

[Appendix A: A1- List of International Standards in Metrology](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[Note](#)

[6 Tolerance Stack-Up Analysis](#)

[6.1 Introduction](#)

[6.2 Brief Introduction to Geometric Dimensioning and Tolerancing \(GD&T\)](#)

[6.3 Tolerance Format and Decimal Places](#)

[6.4 Converting Plus/Minus Dimensions and Tolerances into Equal-Bilaterally Toleranced Dimensions](#)

[6.5 Tolerance Stack Analysis](#)

[6.6 Statistical Tolerance Analysis](#)

[Appendix A from ISO and ASME Y14 Symbols](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[7 Instrument Calibration Methods](#)

[7.1 Introduction](#)

[7.2 Definition of Calibration](#)

[7.3 Need for Calibration](#)

[7.4 Characteristics of Calibration](#)

[7.5 Calibration Overall Requirements and Procedures](#)

[7.6 Calibration Laboratory Requirements](#)

[7.7 Industry Practices and Regulations](#)

[7.8 Calibration and Limitations of a Digital System](#)

[7.9 Verification and Calibration of CNC Machine Tool](#)

[7.10 Inspection of the Positioning Accuracy of CNC Machine Tools](#)

[7.11 CNC Machine Error Assessment and Calibration](#)

[7.12 Assessment of the Contouring in the CNC Machine Using a Kinematic Ballbar System](#)

[7.13 Calibration of 3-axis CNC Machine Tool](#)

[7.14 Calibration of a Coordinate Measuring Machine \(CMM\)](#)

[Section 1: Scope and Description](#)

[Section 2: Calibration Requirements](#)

[Section 3: Preliminary Operations](#)

[Section 4: Calibration Process](#)

[Section 5: Data Analysis](#)

[Section 6: Calibration Report](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[Notes](#)

[8 Uncertainty in Measurements](#)

[8.1 Introduction and Background](#)

[8.2 Uncertainty of Measurement](#)

[8.3 Measurement Error](#)

[8.4 Why Is Uncertainty of Measurement Important?](#)

[8.5 Components and Sources of Uncertainty](#)

[8.6 Static Errors and Dynamic Errors](#)

[8.7 Types of Uncertainty](#)

[8.8 Uncertainty Evaluations and Analysis](#)

[8.9 Uncertainty Reporting](#)

[8.10 How to Report Uncertainty](#)

[8.11 Fractional Uncertainty Revisited](#)

[8.12 Propagation of Uncertainty](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[9 Dimensional Measurements and Calibration](#)

[9.1 Length Measurement](#)

[9.2 Displacement Measurement](#)

[9.3 Manual Instruments](#)

[9.4 Diameter and Roundness](#)

[9.5 Angular Measurements](#)

[9.6 Metrology for Complex Geometric Features](#)

[9.7 Measurement Surface Texture](#)

[Multiple Choice Questions of this Chapter](#)
[References](#)

[10 Mechanical Measurements and Calibration](#)

[10.1 Importance of Mechanical Measurements](#)
[10.2 Mechanical Measurements and Calibration](#)
[10.3 Description of Mechanical Instruments](#)
[10.4 Calibration of Mechanical Instruments](#)
[10.5 Equipment Validation for Measurement](#)
[10.6 Difference between Calibration and Validation of Equipment](#)
[10.7 Difference between Calibration and Verification](#)
[10.8 Calibration of Each Instrument](#)

[Multiple Choice Questions of this Chapter](#)
[References](#)

[11 Thermodynamic Measurements](#)

[11.1 Background](#)
[11.2 Scale of Temperature](#)
[11.3 Power](#)
[11.4 Enthalpy](#)
[11.5 Humidity Measurements](#)
[11.6 Methods of Measuring Temperature](#)
[11.7 Temperature Measured through Thermal Expansion Materials](#)
[11.8 Thermoelectric Temperature Measurement or Thermocouples](#)
[11.9 Thermocouple Materials](#)
[11.10 Multi-Junction Thermocouple Circuits](#)
[11.11 Thermopiles](#)

[11.12 Radiative Temperature Measurement](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[12 Quality Systems and Standards](#)

[12.1 Introduction to Quality Management](#)

[12.2 Quality Management](#)

[12.3 Components of Quality Management](#)

[12.4 System Components](#)

[12.5 Quality Standards and Guides](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[13 Digital Metrology Setups and Industry Revolution](#)

[I4.0](#)

[13.1 Introduction](#)

[13.2 Data Acquisition](#)

[13.3 Setup Fundamentals for Measurement and Data Acquisition](#)

[13.4 Digital Twin Metrology Inspection](#)

[Multiple Choice Questions of this Chapter](#)

[References](#)

[Index](#)

[End User License Agreement](#)

List of Tables

Chapter 1

[Table 1.1 Primary units.](#)

[Table 1.2 Derived units.](#)

[Table 1.3 SI Units and prefixes.](#)

[Table 1.4 Standards of conformity assessment tools.](#)

Chapter 2

[Table 2.1 Major nanometrological instruments and their related resolution ra...](#)

Chapter 3

[Table 3.1 Table conversion of distance imperial/metric.](#)

[Table 3.2 Table conversion of mass imperial/metric.](#)

[Table 3.3 Angular conversion to degrees.](#)

[Table 3.4 Table of various chart needed in Engineering, courtesy of tmssoftw...](#)

[Table 3.5 Variable \$z\$ vs. confidence level.](#)

[Table 3.6 Table of Normal \$z\$ distribution.](#)

[Table 3.7 Table of Student's \$t\$ -distribution.](#)

[Table 3.8 Excerpt from Student's \$t\$ distribution table.](#)

Chapter 4

[Table 4.1 Preliminary error budget table.](#)

[Table 4.2 Error-budget table.](#)

[Table 4.3 Error-budget table.](#)

[Table 4.4 Current AFM specifications.](#)

[Table 4.5 Errors budget table.](#)

[Table S4.1](#)

Chapter 5

[Table 5.1 Standard scale of sizes.](#)

[Table 5.2 Comparison between 3 different techniques and ranges measuring str...](#)

[Table 5.3 Types of CMM configuration -1](#)

[Table 5.4 Types of CMM configuration -2](#)

[Table 5.5](#)

[Table 5.6 Actual Size = 15.0000 mm; Tolerance = 0.05.](#)

[Table 5.7 Inspection methodologies as discussed with Creaform.](#)

Chapter 6

[Table 6.1](#)

[Table 6.2](#)

[Table 6.3](#)

[Table 6.4](#)

[Table 6.5 Tolerance stack of swing weight governor.](#)

[Table 6.6 Tolerance stack.](#)

Chapter 7

[Table 7.1 Recommended environmental conditions.](#)

[Table 7.2 Initial environmental conditions](#)

[Table 7.3 Raw data collected by laser interferometer measurements.](#)

[Table 7.4 Pitch Motion Error \(Raw Data\).](#)

[Table 7.5 Further Calculated Values from the Calibration.](#)

[Table 7.6](#)

[Table 7.7](#)

[Table 7.8](#)

[Table 7.9 Specification of Laser Interferometer](#)

[Table 1. CALIBRATION DESCRIPTION](#)

[Table 2. CALIBRATION EQUIPMENT](#)

Chapter 8

[Table 8.1 Sample of uncertainty reporting
\(Courtesy of Fluke\).](#)

Chapter 9

[Table 9.1 Capacitance characteristics.](#)

[Table 9.2 LVDT, RVDT characteristics.](#)

[Table 9.3 Laser interferometry characteristics.](#)

[Table 9.4 Results of roundness measurements.](#)

[Table 9.5 The measured results and the uncertainty
of measurements](#)

[Table 9.6 Comparison of inspection results.](#)

[Table 9.7 Relationship between surface parameters
and sampling length \(ISO 4...](#)

Chapter 10

[Table 10.1 Force transducer types and ranges \[2\].](#)

[Table 10.2 Excerpt from The Modal Shop's
published ISO 17025 A2LA certified ...](#)

Chapter 11

[Table 11.1 Pressure units' conversion.](#)

[Table 11.2 Basic thermocouple materials.](#)

Chapter 12

[Table 12.1 Standards.](#)

Chapter 13

[Table 13.1 Sensors with related signal conditioning
needed.](#)

Table 13.2

List of Illustrations

Chapter 1

Figure 1.1 Simplified methodology producing measurement results.

Figure 1.2 Vitruvian man by Leonardo da Vinci showing nine historical units ...

Figure 1.3 The standard kilogram for mass.

Figure 1.4 The platinum-iridium meter bar reference.

Chapter 2

Figure 2.1 Overall scale of metrology.

Figure 2.2 Scale range at various levels.

Figure 2.3 Metrological scanning probe microscope.

Figure 2.4 SEM image of nanoporous anodic alumina membrane and ZnO fibers.

Figure 2.5 Nano-manipulator with monitors and robotics controllers.

Figure 2.6 Micro-actuator, box and electronic circuit. Courtesy of Fotofab....

Figure 2.7 Micro-actuator, box and electronic circuit. Courtesy of Fotofab....

Figure 2.8 Extremely large aspect ratio microtool.

Figure 2.9 Laser printed dots @ 1 μm resolution with CCD imaging. H...

[Figure 2.10 Simple ruler in SI and Imperial units to measure length.](#)

[Figure 2.11 Coordinate measuring machine inspecting a part.](#)

[Figure 2.12 Ballbar instrument to inspect motion in CNC machines.](#)

[Figure 2.13 Fuselage and wind mill needing LSM.](#)

[Figure 2.14 Bending of a laser light over a length L.](#)

[Figure 2.15 Spherical retro reflector for laser trackers \(courtesy of API\)....](#)

[Figure 2.16 Bending measuring tape over the whole length to be measured.](#)

[Figure 2.17 Large-scale metrology systems.](#)

[Figure 2.18 CMM for car geometry inspection \(LK\).](#)

[Figure 2.19 Theodolite \(courtesy of Leica\).](#)

[Figure 2.20 Measurement principle of iGPS.](#)

Chapter 3

[Figure 3.1 Calibration figure.](#)

[Figure 3.2 Perimeter of square, circle, and triangle.](#)

[Figure 3.3 Areas of various figures.](#)

[Figure 3.4 Volumes of various figures.](#)

[Figure 3.5 Sample taken from a population.](#)

[Figure 3.6 Statistical data for diameter measurements.](#)

[Figure 3.7 Normal Distribution.](#)

[Figure 3.8 Probability density function.](#)

Figure 3.9 Areas under the curve between 0 and various values.

Figure 3.10 Probability distribution for the t -statistic.

Chapter 4

Figure 4.1 Example of measurements.

Figure 4.2 Graphical representation of a resolution.

Figure 4.3 Repeatability.

Figure 4.4 Systematic error is larger than the typical random error.

Figure 4.5 Typical random error is larger than the systematic error.

Figure 4.6 Example of error on linear movement.

Figure 4.7 Total error of a linear slide. One-dimensional uncertainty.

Figure 4.8 a) Planar error, b) Volumetric error.

Figure 4.9 Various sources of errors affecting the accuracy of a work piece....

Figure 4.10 Typical thermal deformation of horizontal motor spindle.

Figure 4.11 Thermal Errors affecting structure of a machine tool.

Figure 4.12 Examples of Abbé errors in measurement using a caliper.

Figure 4.13 Measurement spectrum.

Figure 4.14 General procedure for error compensation.

[Figure 4.15 Transformation from original to current coordinates.](#)

[Figure 4.16 3D axis system with unit vectors.](#)

[Figure 4.17 3D axis system with unit vectors.](#)

[Figure 4.19 Six degrees of freedom error motion of 3D stage.](#)

[Figure 4.20 Schematic of the integrated manipulator and overall coordinate s...](#)

[Figure 4.21 3D axis configuration of the nano-manipulator.](#)

[Figure 4.22 Configuration of the nanomanipulator.](#)

[Figure 4.23 Manipulator's tip \$t_1\$...](#)

[Figure 4.24 Schematic views of experimental a\) rotational errors and b\) tran...](#)

[Figure 4.25 Error progression over one rotation in x and y directions.](#)

[Figure 4.26 Eccentricity error before \(a\) and after compensation \(b\) of the ...](#)

[Figure 4.27 Calibrating reference 2x2 \$\mu\text{m}\$ squares.](#)

[Figure 4.28 Background noise of the probe tip at 20°C.](#)

Chapter 5

[Figure 5.1 Measurement Process.](#)

[Figure 5.2 Unbroken chain of comparisons leading to quantitative information...](#)

[Figure 5.3 Physical measurement process.](#)

[Figure 5.4 Relative scale of five items.](#)

[Figure 5.5 Schematic diagram of a digital DC voltmeter.](#)

[Figure 5.6 Michelson interferometer.](#)

[Figure 5.7 Laser interferometer configuration for displacement measurement....](#)

[Figure 5.8 Laser interferometer configuration for displacement measurement....](#)

[Figure 5.9 Laser interferometer configuration for angular measurement.](#)

[Figure 5.11 Associated errors for a 3-axis machine. \[Courtesy of HP\].](#)

[Figure 5.12 Principle of driving a table with servo control.](#)

[Figure 5.13 6 main errors associated to 1-axis moving table in CNC machine....](#)

[Figure 5.14 Corresponding physical Renishaw interferometer.](#)

[Figure 5.15 Vertical straightness measured in CNC machine tool using laser i...](#)

[Figure 5.16 Vertical straightness measured in CNC machine tool using a strai...](#)

[Figure 5.17 Positioning error of the machine spindle.](#)

[Figure 5.18 Measurement errors in axis a\) Position, b\) Straightness, c\) Pitc...](#)

[Figure 5.19 Horizontal arm inconvenience due to center of gravity CG.](#)

[Figure 5.20 Robot arms CMM \(Faro and Romer\).](#)

[Figure 5.21 Configuration of CMM in coordinate measuring system.](#)

[Figure 5.22 Touch probe system.](#)

[Figure 5.23 Features to inspect.](#)

[Figure 5.24 Fundamental touch probe.](#)

[Figure 5.25 Error E of the probe at angle \$\theta\$.](#)

[Figure 5.26 Measurement touch probe -OSP60 \(Renishaw\) and Metris scan probe....](#)

[Figure 5.27 Source of dynamic errors in touch probes.](#)

[Figure 5.28 Form error in low and high measurement speed probing.](#)

[Figure 5.29 Resolution of the feature depending on the resolution of the sca...](#)

[Figure 5.30 A\) CMM inspecting a motor. B\) Close view to the probe.](#)

[Figure 5.31 Digital manufacturing and inspection.](#)

[Figure 5.32 Stylus qualification and Probing strategy.](#)

[Figure 5.33 Probing most common mistakes to avoid.](#)

[Figure 5.34 Basic probing for features.](#)

[Figure 5.35 Scan-to-CAD of the part.](#)

[Figure 5.36 CAD file with GD&T and 3D scan of the part.](#)

[Figure 5.37 Sample part with full inspection in distributed errors.](#)

[Figure 5.38 Partial inspection report \(courtesy of CREAFORM\).](#)

[Figure 5.39 Part to CAD inspection.](#)

[Figure 5.40 Various 3D scanner categories from CREAFORM.](#)

[Figure 5.41 Tracked 3D scanner from CREAFORM](#)

[Figure 5.42 Target part to ReCAD.](#)

[Figure 5.43 3D scan and model RE-CAD for the purpose.](#)

[Figure 5.44 Inspection report \(courtesy CREAFORM\) Future of CMM with robotic...](#)

[Figure 5.45 Reference frame 1](#)

[Figure 5.46 Surface 1-1 - Reference frame 1.](#)

[Figure 5.47 Surface 1-2 - Reference frame 1.](#)

[Figure 5.48 Orbit system comprising monitor, interface module and LVDT senso...](#)

[Figure 5.49 Magnetic holder and Optical Table.](#)

[Figure 5.50 Experimental measurement.](#)

[Figure 5.51 Schematic of the test.](#)

Chapter 6

[Figure 6.1 Effect of tolerances on manufacturing and specifications of the m...](#)

[Figure 6.2 Cost of technical drawing error](#)

[Figure 6.3 Manufacturing cost depending on the nominal tolerance for steel....](#)

[Figure 6.4 Sanitary needle.](#)

[Figure 6.5 Sanitary needle- side view.](#)

[Figure 6.6 a\) Dimensions and b\) intermediate reference dimension \[ASME Y14.5...](#)

[Figure 6.7 Repetitive features and dimensions \[ASME Y14.5\].](#)

[Figure 6.8 Dimensions and positional tolerancing with datum references \[ASME...](#)

[Figure 6.9 Technical drawing of a workpiece.](#)

[Figure 6.10 Technical drawing of a workpiece \[ASME Y14.5\].](#)

[Figure 6.11 Dimensions of a part. \[ASME Y14.5\].](#)

[Figure 6.12 Unilateral tolerance](#)

[Figure 6.13 Bilateral tolerance](#)

[Figure 6.14 Compound tolerance](#)

[Figure 6.16 Moving from dimensions with SLOF to GD&T.](#)

[Figure 6.17 Feature control frame placement \[ASME Y14.5\].](#)

[Figure 6.18 Components of the feature control frame.](#)

[Figure 6.19 Component with GD&T control.](#)

[Figure 6.20 Tolerance range specified plus/minus tolerances](#)

[Figure 6.21 GD&T tolerance and equivalent normal tolerance.](#)

[Figure 6.22 Accumulation of tolerances on a drawing.](#)

[Figure 6.23 Shift about the fastener in part 2.](#)

[Figure 6.24 Accumulation of tolerances on a drawing.](#)

[Figure 6.25 Accumulation of tolerances on a drawing.](#)

[Figure 6.26 Accumulation of tolerances on a drawing.](#)

[Figure 6.27 Missing dimension and tolerance in a part.](#)

[Figure 6.28 Chain of dimensions and tolerances.](#)

[Figure 6.29 Chain of dimensions and tolerances.](#)

[Figure 6.30 Chain of dimensions and tolerances.](#)

[Figure 6.31 Gaussian distribution of a toleranced dimension\(s\).](#)

[Figure 6.32 Accumulation of tolerances on a drawing.](#)

[Figure 6.33 Accumulation of tolerances on a drawing.](#)

[Figure 6.34 Accumulation of tolerances on a drawing.](#)

[Figure 6.35](#)

[Figure 6.36 MMC for tolerance allowed at a\) MMC and b\) MMC to a datum.](#)

[Figure 6.37 RFS example of flatness remaining constant irrespective of the d...](#)

[Figure 6.38 Sample of tolerance for fit parts.](#)

[Figure 6.39 Gauging the pin.](#)

[Figure 6.40 Snapshot of the wheel assembly and functional gap.](#)

[Figure 6.41 Snapshot of stack-up analysis improved gap in CREO software \(Sig...](#)

[Figure 6.42](#)

[Figure 6.43 Results of the simulation.](#)

[Figure 6.44 Assembly](#)

[Figure 6.45 a\) Crankshaft assembly. b\) Drawing.](#)

[Figure 6.46 Crankshaft assembly.](#)

[Figure 6.47 Crankshaft assembly.](#)

[Figure 6.48 Crankshaft assembly.](#)

[Figure 6.49 Crankshaft assembly.](#)

Chapter 7

[Figure 7.1 Initial circular dividing engine.](#)

[Figure 7.2 Calibration components.](#)

[Figure 7.3 Static calibration curve.](#)

[Figure 7.4 Traceability route.](#)

[Figure 7.5 Zero error calibration.](#)

[Figure 7.6 Linearity error calibration.](#)

[Figure 7.7 Digital sampling @ 30° intervals.](#)

[Figure 7.8 Aliasing digital sampling @ 390° intervals giving a long sine wav...](#)

[Figure 7.9 Results graphs obtained by the ballbar exhibiting the different e...](#)

[Figure 7.10 Ballbar traceability chart.](#)

[Figure 7.11 Positioning accuracy of a CNC machining center using laser inter...](#)

[Figure 7.12 The bidirectional pendulum target sequence.](#)

[Figure 7.13 - Test Cycle Executed.](#)

[Figure 7.14 a\) X-axis Positional Error \(Forward\), b\) X-axis Positional Error...](#)

[Figure 7.15 Pitch motion error.](#)

[Figure 7.16 Compensated positioning.](#)

[Figure 7.17 Experimental set-up.](#)

[Figure 7.18 a\) Axes of TC 600 with turret disc BMT45. The x- and z-axis of t...](#)

[Figure 7.19 X-Axis TC 600 with laser interferometry configured.](#)

[Figure 7.20 Z-Axis TC 600 with laser interferometry configured.](#)

[Figure 7.21 Non-compensated X-axis CNC TC 600 \(courtesy Spinner\).](#)

[Figure 7.22 Compensated X-axis CNC TC 600 \(courtesy Spinner\).](#)

[Figure 7.23 Non compensated Z-axis CNC TC 600 \(courtesy Spinner\).](#)

[Figure 7.24 Compensated Z-axis CNC TC 600 \(courtesy Spinner\).](#)

[Figure 7.25 Coordinate measuring machine \(CMM\).](#)

[Figure 7.26 Probing exist inside CNC machine tool.](#)

[Figure 7.27 Step gauge with CMM calibration.](#)

[Figure 7.28 Measuring lines for CMM verification.](#)

[Figure 7.29 One line \$N_1\$ test \(3 times\) for CMM verification.](#)

Chapter 8

[Figure 8.1 Example of uncertainty A.](#)

[Figure 8.2 Propagation of error with respect to variable \$x\$.](#)

Chapter 9

[Figure 9.1 Capacitance sensor.](#)

[Figure 9.2 LVDT sensor](#)

[Figure 9.3 Michelson interferometer.](#)

[Figure 9.4 Interference pattern.](#)

[Figure 9.5 A caliper](#)

[Figure 9.6 a\) Vernier caliper and digital caliper. b\). Associated Abbe error....](#)

[Figure 9.7 A micrometer \(courtesy of Mahr\).](#)

[Figure 9.8 Feeler gauge with multiple stripes.](#)

[Figure 9.9 Liner Measurement Tool.](#)

[Figure 9.10 Wire gage.](#)

[Figure 9.11 Dial and digital bore gauge.](#)

[Figure 9.12 Telescopic gauge.](#)

[Figure 9.13 Digital and dial depth gauge.](#)

[Figure 9.14 An angle plate.](#)

[Figure 9.15 Flat plate. Cast iron surface plate, the underside.](#)

[Figure 9.16 Angle plate dial and digital.](#)

[Figure 9.17 Oil Gauging Tapes.](#)

[Figure 9.18 Thread definition, metric manual thread device and CMM thread in...](#)

[Figure 9.19 Planimeter.](#)

[Figure 9.20 External diameter measurement.](#)

[Figure 9.21 External diameter measurement.](#)

[Figure 9.22 External and internal roundness.](#)

[Figure 9.23 Hydrodynamic bearing with internal rotating shaft.](#)

[Figure 9.24 Out-of-roundness measured in \(a\) outer diameter and \(b\) inner di...](#)

[Figure 9.25 Hydrodynamic bearing with internal rotating shaft.](#)

[Figure 9.26 Hydrodynamic bearing with internal rotating shaft.](#)

[Figure 9.27 Setup of the workpiece on the Talyrond machine.](#)

[Figure 9.28 Roundness measurement.](#)

[Figure 9.29 Cylindricity measurement](#)

[Figure 9.30 Configuration for roundness measurement](#)

[Figure 9.31 Universal bevel protractor \(optionally optical\).](#)

[Figure 9.32 Samples of angle measurements.](#)

[Figure 9.33 Sine bar.](#)

[Figure 9.34 Sine center.](#)

[Figure 9.35 Samples of angle measurements.](#)

[Figure 9.36 Professional digital inclinometer with a resolution of 0.1 degree...](#)

[Figure 9.37 Inclinometer sensor.](#)

[Figure 9.38 Vernier clinometer](#)

[Figure 9.39 Clinometer apps on google play.](#)

[Figure 9.40 Optical comparators](#)

[Figure 9.41 Physical and Schematic of an Autocollimator.](#)

[Figure 9.42 Selected region for the inspection.](#)

[Figure 9.43 Reverse engineered scanning to obtain 3D CAD file \(Courtesy of C...](#)

[Figure 9.44 Features measurement and modification if needed. \(Courtesy of Cr...](#)

[Figure 9.45 Full digital inspection of a reversed part.](#)

[Figure 9.46 A surface texture representing the combined effects of several c...](#)

[Figure 9.47 Various profiles having the same amplitude at different waveleng...](#)

[Figure 9.48 Comparison of the above filters.](#)

[Figure 9.49 Surface profile parameters](#)

[Figure 9.50 Stylus instrument \(ISO 3274\).](#)

[Figure 9.51 Handy surface finish equipment \(courtesy Taylor-Hobson\).](#)

Chapter 10

[Figure 10.1 Open loop transducer weight system.](#)

[Figure 10.2 Strain gauge in Wheatstone bridge.](#)

[Figure 10.3 Signal outcome of the strain gauge in Wheatstone bridge.](#)

[Figure 10.4 Dynamic mass-spring system.](#)

[Figure 10.5 Hydrometer.](#)

[Figure 10.6 Noise measurement instrument.](#)

[Figure 10.7 Sample of noise measurement in a compressor.](#)

[Figure 10.8 Noise modeling generated in pressurized air flow in a pipe using...](#)

[Figure 10.9 Absolute configuration](#)

Chapter 11

[Figure 11.1 Temperature scale.](#)

[Figure 11.2 Liquid-in-glass thermometer.](#)

[Figure 11.3 Bimetallic thermometer.](#)

[Figure 11.4 Temperature based on resistance for selected materials \[1\].](#)

[Figure 11.5 Wire-wound RTD.](#)

[Figure 11.6 Thin film RTD.](#)

[Figure 11.7 RTD Wheatstone bridge arrangement.](#)

[Figure 11.8 Thermistor types.](#)

[Figure 11.9 Basic thermocouple circuit.](#)

[Figure 11.10 intermediate metals.](#)

[Figure 11.11 Intermediate temperatures.](#)

[Figure 11.12 Type J thermocouple circuit.](#)

[Figure 11.13 Thermopile arrangement \[2\].](#)

[Figure 11.14 Thermopiles in series and in star connection.](#)

[Figure 11.15 Thermal radiation spectrum.](#)

[Figure 11.16 Capture of the temperature distribution of a Peltier cooler. Ra...](#)

[Figure 11.17 Principle of thermal camera.](#)

Chapter 12

[Figure 12.1 Principles of quality standards.](#)

[Figure 12.2 Quality system, quality assurance and quality control associatio...](#)

[Figure 12.3 Evaluation of needs.](#)

Chapter 13

[Figure 13.1 Measurement Process.](#)

[Figure 13.2 Measurement Process.](#)

[Figure 13.3 A block diagram of a typical instrumentation system with several...](#)

[Figure 13.4 Basic sensor configuration in measurement with data transmission...](#)

[Figure 13.5 PC based temperature and data acquisition system.](#)

[Figure 13.6 Open loop inspection and reporting.](#)

[Figure 13.7 Various stages of data transmission.](#)

[Figure 13.8 Advanced sensor configuration in measurement.](#)

[Figure 13.9 Advanced sensor configuration for in-process inspection.](#)

[Figure 13.10 Differential Doppler technique probe and its location on Takisa...](#)

[Figure 13.11 Integrated concept for the next generation of machine tool cent...](#)

[Figure 13.12 Concept of Cyber-Physical Manufacturing Model \(CPM³\).](#)

Wiley-ASME Press Series

Fabrication of Process Equipment

Owen Greulich, Maan H. Jawad

Engineering Practice with Oilfield and Drilling Applications

Donald W. Dareing

Flow-Induced Vibration Handbook for Nuclear and Process Equipment

Michel J. Pettigrew, Colette E. Taylor, Nigel J. Fisher

Vibrations of Linear Piezostructures

Andrew J. Kurdila, Pablo A. Tarazaga

Bearing Dynamic Coefficients in Rotordynamics:

Computation Methods and Practical Applications

Lukasz Brenkacz

Advanced Multifunctional Lightweight Aerostructures:

Design, Development, and Implementation

Kamran Behdinan, Rasool Moradi-Dastjerdi

Vibration Assisted Machining: Theory, Modelling and Applications

Li-Rong Zheng, Dr. Wanqun Chen, Dehong Huo

Two-Phase Heat Transfer

Mirza Mohammed Shah

Computer Vision for Structural Dynamics and Health Monitoring

Dongming Feng, Maria Q Feng

Theory of Solid-Propellant Nonsteady Combustion

Vasily B. Novozhilov, Boris V. Novozhilov

Introduction to Plastics Engineering

Vijay K. Stokes

Fundamentals of Heat Engines: Reciprocating and Gas
Turbine Internal Combustion Engines

Jamil Ghojel

Offshore Compliant Platforms: Analysis, Design, and
Experimental Studies

Srinivasan Chandrasekaran, R. Nagavinothini

Computer Aided Design and Manufacturing

Zhuming Bi, Xiaoqin Wang

Pumps and Compressors

Marc Borremans

Corrosion and Materials in Hydrocarbon Production: A
Compendium of Operational and Engineering Aspects

Bijan Kermani and Don Harrop

Design and Analysis of Centrifugal Compressors

Rene Van den Braembussche

Case Studies in Fluid Mechanics with Sensitivities to
Governing Variables

M. Kemal Atesmen

The Monte Carlo Ray-Trace Method in Radiation Heat
Transfer and Applied Optics

J. Robert Mahan

Dynamics of Particles and Rigid Bodies: A Self-Learning
Approach

Mohammed F. Daqaq

Primer on Engineering Standards, Expanded Textbook
Edition

Maan H. Jawad and Owen R. Greulich

Engineering Optimization: Applications, Methods and
Analysis

R. Russell Rhinehart

Compact Heat Exchangers: Analysis, Design and
Optimization using FEM and CFD Approach
C. Ranganayakulu and Kankanhalli N. Seetharamu

Robust Adaptive Control for Fractional-Order Systems with
Disturbance and Saturation
Mou Chen, Shuyi Shao, and Peng Shi

Robot Manipulator Redundancy Resolution
Yunong Zhang and Long Jin

Stress in ASME Pressure Vessels, Boilers, and Nuclear
Components
Maan H. Jawad

Combined Cooling, Heating, and Power Systems: Modeling,
Optimization, and Operation
Yang Shi, Mingxi Liu, and Fang Fang

Applications of Mathematical Heat Transfer and Fluid Flow
Models in Engineering and Medicine
Abram S. Dorfman

Bioprocessing Piping and Equipment Design: A Companion
Guide for the ASME BPE Standard
William M. (Bill) Huitt

Nonlinear Regression Modeling for Engineering
Applications: Modeling, Model Validation, and Enabling
Design of Experiments
R. Russell Rhinehart

Geothermal Heat Pump and Heat Engine Systems: Theory
and Practice
Andrew D. Chiasson

Fundamentals of Mechanical Vibrations
Liang-Wu Cai

Introduction to Dynamics and Control in Mechanical
Engineering Systems